1983 Editorial Index

BUILDING REMODELING/RETROFIT • ENERGY MANAGEMENT • LIGHTING • LIFE SAFETY/SECURITY • FLOOR SELECTION & CARE • MAINTENANCE

BUILDING REMODELING/RETROFIT

Renovating the Envelope — Jan 28
Commercial Doors — Jan. 39
Door Retrofit (case study) — Jan. 50
Door Retrofit (case study) — Jan. 52
Door Retrofit (case study) — Jan. 54
Signage System Guidelines — Jan. 56
Roof Moisture Analysis — Jan. 62
Exterior Wall System (case study) — Jan. 70
Remodeling Public Areas — Feb. 16
Washroom Renovation — Feb. 34
Retrofit Roofing System — Feb. 72
Restroom Fixture Retrofit (case study) — Feb. 76
Interior Storm Windows (case study) — Feb. 84
Energy-Efficient Building Design — March 71
Fiber Optics Data Transmission Network — March 90
Energy Management System (case study) — March 94
Energy Management System (case study) — March 98
Combustion Efficiency Computer Retrofit — March 102
Low Pressure Sodium Lighting Retrofit (case study) — March 104
Energy Management System Cooling System Retrofit (case study) — March 106
Energy Management System Retrofit (case study) — March 108
Building Automation System Retrofit (case study) — March 110
Building Management System (case study) — March 112
Energy Management Plan (case study) — March 114
Restoration Lighting Design — May 16
Retrofitting Exterior Lighting — May 26
Office Lighting Options — May 62
HID Lighting Retrofit (case study) — May 88
Metal Halide Lighting Retrofit (case study) — May 90
Flood Lamp Conversion (case study) — May 98
Exterior Aluminum Cladding (case study) — May 100
Window Restoration Program (case study) — May 102
Remodeling Office Space — June 18
Office Lighting Trends — June 32
The Renovation Process — June 42
Office Space Planning — June 52
Design of Office Environment — June 60
Interior Plantscaping — June 66
Relocatable Wall Systems — June 74
Heat Pump Retrofit (case study) — June 90
Indirect Lighting Installation (case study) — July 80
Solar Window Screen Installation (case study) — July 83
Single-Ply Roof Retrofit (case study) — July 84
The "Flame-Resistant Hotel Room" — Aug. 50
Security Hardware Retrofit — Aug. 66
Fire/Smoke Control System (case study) — Aug. 78
Triple-Glazed Window Retrofit (case study) — Aug. 85
Kittridge Building Preservation (case study) — Sept. 14
Guaranty Building Restoration (case study) — Sept. 22
1st Business Bank Renovation (case study) — Sept. 30
Quincy Mall Renovation (case study) — Sept. 36
Danbury Mill Rehab (case study) — Sept. 40
Paul Brown Building Restoration (case study) — Sept. 42
Vincent J. Doyle Manor Adaptive Reuse (case study) — Sept. 44
Community Medical Center Renovation (case study) — Sept. 48
Simpson Hall Reconstruction/Retrofit (case study) — Sept. 52
19 Court Plaza Renovation (case study) — Sept. 68
Energy-Efficient School Renovation — Sept. 72
Elevator Modernization Survey — Sept. 80
Selecting a Contractor — Sept. 90
Construction Management vs. Project Management — Sept. 98
Life Cycle Cost Considerations in Material Selection — Sept. 108
'83 Remodeling/Replacement Survey — Sept. 120
VAV System Retrofit (case study) — Sept. 144
Urethane Foam Roofing — Oct. 70
Single-ply Roofing — Oct. 76
Roofing: End-User Survey — Oct. 92
Hospital Re-Roofing (case study) — Oct. 102
Automated Lighting Control System (case study) — Oct. 106
Computerized Building Information System — Nov. 16
Custom-Designed Office Furniture — Nov. 26
Office Furniture & Equipment — Nov. 42
Specifying Commercial Carpeting — Nov. 54
Tenant Development — Nov. 62
Carpet Replacement — Nov. 82
Chiller Retrofit (case study) — Nov. 102
Combustion Trim Controls for Small Packaged Boilers — Dec. 34
Heat Pump System Retrofit (case study) — Dec. 72
Boiler Retrofit (case study) — Dec. 76
Thermostatic Radiator Valve Retrofit (case study) — Dec. 80
Single-Ply Roof Retrofit (case study) — Dec. 82

ENERGY MANAGEMENT

Exterior Wall Systems (case study) — Jan. 70
Energy Management System (case study) — Jan. 74
Window Film (case study) — Feb. 78
Window Glazing System (case study) — Feb. 80
Interior Storm Windows (case study) — Feb. 84
'83 ASHRAE Energy Award Winner: Austin Co. — March 24
Chilled Water Storage System (case study) — March 34
Chilled Water Storage — March 35
Energy Management Planning — March 42
EMS Alternatives — March 50
Energy Saving Control Systems — March 58
EMS Operation & Maintenance Costs — March 66
Energy-Efficient Building Design — March 71
Energy Conservation for Smaller Businesses — March 76
Ultrasonic Detection: Energy-Saving Maintenance Tool — March 86
Energy Management System (case study) March 94
Energy Management System (case study) — March 98
Combustion Efficiency Computer Retrofit (case study) — March 102
Cooling System Retrofit (case study) — March 106
Energy Management System Retrofit (case study) — March 108
Building Automation System Retrofit (case study) — March 110
Building Management System (case study) — March 112
Energy Management Plan (case study) — March 114
U.S. Department of Energy Study — March 120
Energy Management Lease Program (case study) — March 124
Hospital Emergency Power Retrofit (case study) — April 131
Lighting Controls — May 52
Energy Accounting Systems — June 28
Heat Pump Retrofit (case study) — June 90
Boiler Care — July 34
Computerized Preventive Maintenance — July 58
Energy-Saving Lighting Retrofit (case study) — July 75

(continued)

1983 Editorial Index

BUILDING REMODELING/RETROFIT • ENERGY MANAGEMENT • LIGHTING • LIFE SAFETY/SECURITY • FLOOR SELECTION & CARE • MAINTENANCE

BUILDING REMODELING/RETROFIT

Renovating the Envelope — Jan 28
Commercial Doors — Jan. 39
Door Retrofit (case study) — Jan. 50
Door Retrofit (case study) — Jan. 52
Door Retrofit (case study) — Jan. 54
Signage System Guidelines — Jan. 56
Roof Moisture Analysis — Jan. 62
Exterior Wall System (case study) — Jan. 70
Remodeling Public Areas — Feb. 16
Washroom Renovation — Feb. 34
Retrofit Roofing System — Feb. 72
Restroom Fixture Retrofit (case study) — Feb. 76
Interior Storm Windows (case study) — Feb. 84
Energy-Efficient Building Design — March 71
Fiber Optics Data Transmission Network — March 90
Energy Management System (case study) — March 94
Energy Management System (case study) — March 98
Combustion Efficiency Computer Retrofit — March 102
Low Pressure Sodium Lighting Retrofit (case study) — March 104
Energy Management System Cooling System Retrofit (case study) — March 106
Energy Management System Retrofit (case study) — March 108
Building Automation System Retrofit (case study) — March 110
Building Management System (case study) — March 112
Energy Management Plan (case study) — March 114
Restoration Lighting Design — May 16
Retrofitting Exterior Lighting — May 26
Office Lighting Options — May 62
HID Lighting Retrofit (case study) — May 88
Metal Halide Lighting Retrofit (case study) — May 90
Flood Lamp Conversion (case study) — May 98
Exterior Aluminum Cladding (case study) — May 100
Window Restoration Program (case study) — May 102
Remodeling Office Space — June 18
Office Lighting Trends — June 32
The Renovation Process — June 42
Office Space Planning — June 52
Design of Office Environment — June 60
Interior Plantscaping — June 66
Relocatable Wall Systems — June 74
Heat Pump Retrofit (case study) — June 90
Indirect Lighting Installation (case study) — July 80
Solar Window Screen Installation (case study) — July 83
Single-Ply Roof Retrofit (case study) — July 84
The "Flame-Resistant Hotel Room" — Aug. 50
Security Hardware Retrofit — Aug. 66
Fire/Smoke Control System (case study) — Aug. 78
Triple-Glazed Window Retrofit (case study) — Aug. 85
Kittridge Building Preservation (case study) — Sept. 14
Guaranty Building Restoration (case study) — Sept. 22
1st Business Bank Renovation (case study) — Sept. 30
Quincy Mall Renovation (case study) — Sept. 36
Danbury Mill Rehab (case study) — Sept. 40
Paul Brown Building Restoration (case study) — Sept. 42
Vincent J. Doyle Manor Adaptive Reuse (case study) — Sept. 44
Community Medical Center Renovation (case study) — Sept. 48
Simpson Hall Reconstruction/Retrofit (case study) — Sept. 52
19 Court Plaza Renovation (case study) — Sept. 68
Energy-Efficient School Renovation — Sept. 72
Elevator Modernization Survey — Sept. 80
Selecting a Contractor — Sept. 90
Construction Management vs. Project Management — Sept. 98
Life Cycle Cost Considerations in Material Selection — Sept. 108
'83 Remodeling/Replacement Survey — Sept. 120
VAV System Retrofit (case study) — Sept. 144
Urethane Foam Roofing — Oct. 70
Single-ply Roofing — Oct. 76
Roofing: End-User Survey — Oct. 92
Hospital Re-Roofing (case study) — Oct. 102
Automated Lighting Control System (case study) — Oct. 106
Computerized Building Information System — Nov. 16
Custom-Designed Office Furniture — Nov. 26
Office Furniture & Equipment — Nov. 42
Specifying Commercial Carpeting — Nov. 54
Tenant Development — Nov. 62
Carpet Replacement — Nov. 82
Chiller Retrofit (case study) — Nov. 102
Combustion Trim Controls for Small Packaged Boilers — Dec. 34
Heat Pump System Retrofit (case study) — Dec. 72
Boiler Retrofit (case study) — Dec. 76
Thermostatic Radiator Valve Retrofit (case study) — Dec. 80
Single-Ply Roof Retrofit (case study) — Dec. 82

ENERGY MANAGEMENT

Exterior Wall Systems (case study) — Jan. 70
Energy Management System (case study) — Jan. 74
Window Film (case study) — Feb. 78
Window Glazing System (case study) — Feb. 80
Interior Storm Windows (case study) — Feb. 84
'83 ASHRAE Energy Award Winner: Austin Co. — March 24
Chilled Water Storage System (case study) — March 34
Chilled Water Storage — March 35
Energy Management Planning — March 42
EMS Alternatives — March 50
Energy Saving Control Systems — March 58
EMS Operation & Maintenance Costs — March 66
Energy-Efficient Building Design — March 71
Energy Conservation for Smaller Businesses — March 76
Ultrasonic Detection: Energy-Saving Maintenance Tool — March 86
Energy Management System (case study) March 94
Energy Management System (case study) — March 98
Combustion Efficiency Computer Retrofit (case study) — March 102
Cooling System Retrofit (case study) — March 106
Energy Management System Retrofit (case study) — March 108
Building Automation System Retrofit (case study) — March 110
Building Management System (case study) — March 112
Energy Management Plan (case study) — March 114
U.S. Department of Energy Study — March 120
Energy Management Lease Program (case study) — March 124
Hospital Emergency Power Retrofit (case study) — April 131
Lighting Controls — May 52
Energy Accounting Systems — June 28
Heat Pump Retrofit (case study) — June 90
Boiler Care — July 34
Computerized Preventive Maintenance — July 58
Energy-Saving Lighting Retrofit (case study) — July 75

(continued)

1983

editorial index

(continued)

HVAC Contract Services (case study) — July 76
Solar Window Screen Installation (case study) — July 83
Air Filtration System Efficiency — July 86
Triple-Glazed Window Retrofit (case study) — July 84
Facility Management System — Sept. 56
HVAC & Lighting System Retrofit (case study) — Sept. 136
Insulation & Solar Retrofit (case study) — Sept. 142
VAV System Retrofit (case study) — Sept. 144
Energy Management Program: Interfirst One — Oct. 19
Assessing Energy Efficiency — Oct. 34
"Energy-from-Waste" Potential — Oct. 42
Energy Loss Control Factors — Oct. 50
Computer-based Facility Management System — Oct. 62
Exterior Insulation & Heat Loss Control — Oct. 98
Saving Energy in Office Buildings — Nov. 34
Chiller Retrofit (case study) — Nov. 102
Lighting Control System (case study) — Nov. 106
Temperature Control Systems — Dec. 18
Steam Trap Payback — Dec. 26
Combustion Trim Controls for Small Packaged Boilers — Dec. 34
Air Conditioning Systems — Dec. 38
Heat Pump System Retrofit (case study) — Dec. 72
Climate Management System (case study) — Dec. 74
Boiler Retrofit (case study) — Dec. 76
Thermostatic Radiator Valve Retrofit (case study) — Dec. 80

LIGHTING

Lighting Public Areas for Safety — Feb. 62
Low Pressure Sodium Lighting Retrofit (case study) — March 104
Restoration Lighting Design — May 16
Retrofitting Exterior Lighting — May 26
Lighting Consultants — May 36
Lighting Lessons Learned — May 46
Lighting Controls — May 52
Office Lighting Options — May 62
Lighting Concepts & Technology — May 78
HID Lighting Retrofit (case study) — May 88
Metal Halide Lighting Retrofit (case study) — May 90
Flood Lamp Conversion (case study) — May 98
Office Lighting Trends — June 32
Energy-Saving Lighting Retrofit (case study) — July 75
Indirect Lighting Installation (case study) — July 80
Lighting Industry Trends — Sept. 118
Lighting & HVAC System Retrofit (case study) — Sept. 136
Automated Lighting Control System (case study) — Oct. 106
CRT's & Office Lighting — Nov. 38
Lighting Control Switches (case study) — Nov. 92
Lighting Control System (case study) — Nov. 106

LIFE SAFETY/SECURITY

Commercial Doors — Jan. 39
Lighting Public Areas for Safety & Security — Feb. 62
Window Glazing System (case study) — Feb. 80
Ceiling Encapsulation (case study) — April 114
Hospital Emergency Power Retrofit (case study) — April 130
24-Hour Security Program — Aug. 16
Contract Security Service (case study) — Aug. 18
Guard Services — Aug. 26
Access Control Systems — Aug. 36
Key Control — Aug. 42
Fire Safety — Aug. 49
The Flame-Resistant Hotel Room — Aug. 50
Computer Security — Aug. 60
Security Hardware Retrofit — Aug. 66
CRT-Based Security System (case study) — Aug. 74
Access Control System (case study) — Aug. 76
Fire/Smoke Control System (case study) — Aug. 78
Fire-Monitoring Panel (case study) — Aug. 80
Fire Barrier Caulking (case study) — Aug. 86
Safety Floor Installation (case study) — Sept. 134

FLOOR SELECTION & CARE

Concrete Floor Coating (case study) — Jan. 76
Avoiding High Cost Maintenance in Public Area Design — Feb. 44
Power Floor Cleaning Equipment — April 60
Floor Stripping Procedures — April 68
Upright Vacs — April 78
Carpet Maintenance Program (case study) — April 108
Interior Carpet Care System — June 82
Carpet Installation (case study) — July 78
Safety Floor Installation (case study) — Sept. 134
Carpet Care — Nov. 50
Specifying Commercial Carpeting — Nov. 54
Resilient Flooring — Nov. 70
Carpet Replacement — Nov. 82
Access Flooring Retrofit (case study) — Nov. 100

EXTERIOR/INTERIOR MAINTENANCE

Masonry Coating Systems — Jan. 18
Exterior Coating (case study) — Jan. 20
Roof Moisture Analysis — Jan. 62
Exterior Coating (case study) — Jan. 72
Concrete Floor Coating (case study) — Jan. 76
Exterior Coating (case study) — Jan. 80
Evaluating Elevator Efficiency — Feb. 26
Avoiding High-Cost Maintenance in Public Area Design — Feb. 44
Landscape Maintenance — Feb. 50
Retrofit Roofing System (case study) — Feb. 72
UltraSonic Detection: An Energy-Saving Maintenance Tool — March 86
Waste Management — April 18
Employee Motivation — April 26
Computerization & Housekeeping Activities — April 32
War on Maintenance Downtime — April 42
Training Maintenance Personnel — April 50
Power Floor Cleaning Equipment — April 60
Floor Stripping Procedures — April 88
Upright Vacs — April 78
The Roof Management Concept — April 86
Roofing Analysis Program (case study) — April 92
Pre-Measured Cleaning Products (case study) — April 98
Contract Maintenance (case study) — April 102
Carpet Maintenance Program (case study) — April 108
Ceiling Encapsulation (case study) — April 114
EPS Roofing Insulation (case study) — April 118
Polyurethane Coating System (case study) — April 123
Managing the Maintenance Function — May 94
Polyester Roofing Fabric (case study) — May 104
Interior Carpet Care System — June 82
Contract Maintenance Services — July 18
Selecting the Landscape Maintenance Contractor — July 24
Boiler Care — July 34
Evaluating Housekeeping Alternatives — July 42
Contract Sweeping — July 50
Computerized Preventive Maintenance — July 58
Contracting for Custodial Maintenance — July 66
Certified Roofing Contractor Program — July 74
HVAC Contract Services (case study) — July 76
Single-Ply Roof Retrofit (case study) — July 84
Insulation Retrofit (case study) — Sept. 140
Urethane Foam Roofing — Oct. 70
Single-Ply Roofing — Oct. 76
Roofing Performance Measurements — Oct. 84
Roofing: End-User Survey — Oct. 92
Exterior Insulation & Heat Loss Control — Oct. 98
Urethane Foam/Coating System (case study) — Oct. 104
Insulation Retrofit (case study) — Oct. 110
Urethane Foam Insulation/Coating System (case study) — Oct. 112
Carpet Care — Nov. 50
Paint Graphics — Nov. 78
Roof Coating (case study) — Nov. 88
Window Overglazing System (case study) — Nov. 110
Power Tools — Dec. 48
Computer-Assisted PM Systems — Dec. 56
Operating & Maintenance Manuals — Dec. 62
Maintenance Program (case study) — Dec. 78
Single Ply Roof Retrofit (case study) — Dec. 82